



Photo shows the existing surface has worn been worn away by vehicles - surface affected by leaf fall from trees along the route of the path.



Photo shows the shared access narrows significantly at this point



The existing footpath which was refurbished some years previous



Photo shows where the existing surface has worn away leaving sizeable potholes - surface water holding in these areas.

Where the shared access meets the existing pedestrian use only part of the footpath

KEY



Area to be resurfaced with 'Flexi-Pave' (including additional links to private properties)

N.B. To be done in 4 day sections as shown.

| Revision number | Date | Description |
|-----------------|------------|-----------------------|
| 1 | 23.01.2017 | Added notes and Key |
| 2 | 25.01.2017 | Amended notes and Key |

| Revision number | Date | Description |
|-----------------|------------|-----------------------|
| 1 | 23.01.2017 | Added notes and Key |
| 2 | 25.01.2017 | Amended notes and Key |

Project: Leeds City Council
 Title: Leeds Footpath No.60 Ch
 Drawn: CAU
 Scale: AS SHOWN
 Date: 05.11.17
 Drawing Number: LD.634.02